

CERTIFIED LAND CORNER RESTORATION


39-12
Index No. PR-13

State of Wisconsin }
County of LANGLADE } ss.

I RAYMOND J. HALLISY, do hereby certify that on the APRIL 27 day of APRIL 27, 1965, I found evidence of the E 1/4 COR.; SE. SEC. COR corner of Sec 21 Township 34N, North, Range 12E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....



○ = Corner monument ~~restored~~. FOUND
X = " SET

History of original corner establishment:

○ E 1/4 COR - REESTABLISHED IN 1936 BY C. W. BORTH.

Description of corner evidence found:

○ E 1/4 COR OLD CAR AXLE - 16" BELOW GROUND LEVEL; BROKE GLASS AROUND AXLE

OLD BT - WH. PINE STUMP 14" S38°W - 172'

Description of monument and accessories I established to perpetuate the original location of this corner.

○ E 1/4 - CORNER REMAINS AS STATED ABOVE
NEW BTS - WH. PINE 18" - N60°15'W 346 LKS
WH. PINE 14" - N74°15'W 301 LKS

X 1/16 CORNER 6" SQ. OAK POST BT OAK 6" - S52°W 21.5 LKS
TRANSIT SURVEY - SEE BACK OF SHEET

Dated at ANTIGO, Wis., this 10 day of JANUARY, 1966.

Signature Raymond J. Hallisy Title Asst. Dist. Surveyor - LOD Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By..... Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE