

CERTIFIED LAND CORNER RESTORATION


Index No. 0-13

State of Wisconsin }  
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 3rd day of July, 19 71, I found evidence of the N 1/16 corner of 21 & 22 Township 34, North, Range 12E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:  
.....  
.....  
.....

FORM 985 R. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Ran transit line from 1/4 Cor. between Sec. 21 & Sec. 22 to Section Corner between 15, 16, 21 & 22. Distance 40.60 chains. Set N 1/16 at 20.30 chains.

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap.

- BT's to corner
  - Hard Maple 4" N3E 19 Feet 8 inches
  - Hard Maple 6" S54E 23 Feet 8 inches
  - Hard Maple 11" S50W 15 Feet 4 inches
- BT's faced at base of tree and scribed BT



Dated at Antigo, Wis., this 3rd day of July, 19 71.

Signature R. J. Hallisy Title Reg. Land Surveyor Registration No. 685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19 \_\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy