## U.S. PUBLIC LAND SURVEY MONUMENT RECORD (Prepared and as required by S. A-E 7.08 W Administrative Code)

The NORTHWEST	corner of Sect	ion 5	5 . т.	33 <sub>N</sub>	R. /2 F	E., Lanaiade County, Wi	
Corner was: (check	_					, Langidad Godiney, iii	
Restored through	h acceptance of a found perm	etuated	locatio	n.			
☐ Determined to b (Show bearing)	e lost and re-established three and distances to PLSS corr	ough pro ners used	oportior d for p	iate metho roportionini	ds. g.)	341231 0000	
Restored/recover	red/reestablished in a locatio osition. (Show difference in pla	n that d	liffers f	rom a prev	viously		
	dditional information is shown ence, recovered physical evide					ial evidence and all other	r evider
onsidered in the re-	covery/restoration of the com	ner.					
ne original corner v	was established in 1857 by A	Ifred Mi	illard.	Original b	earing tree	es were 3 Y. pines: 18",	corner
35°E, 132 links; 18	3", S48°E, 280 links; and a 1 "x 12" x 24" with + on top	2", Nou He als	o mari	zinks. De ced two ne	om, date u ew BT's: n	nknown, described the Gorway, 11", S73°W, 1.5	89
nains, and a norway	7, 12", N82°E, 1.96 chains.	Poss, in	1968,	found stor	ne with cro	oss on top and set a bras	ss cap
concrete witness r	nonument, N75°E, 34.60 fee	et. 08/1	l 1/99 I	D. Tlusty, I	D. William	is, found stone (approx.	12" x
2" x 20" with chise	led "+" on one end) lying or concrete (Poss's witness mo	i ground Snument	on the	east side	oi gravei i • Accepte	road. At 5/5 w, 54.00 ed location of 1" pipe as	the
est evidence of the	corner. Re-set stone found	as a wit	tness m	onument	(see below	y).	
Physical description	of the monument set:		,				
•	pipe with a new 2" x 30" iro	n pipe w	vith 3 ½	4" brass c	ap, top of	which is 0.2' below gro	und
n west side of grave		p-p-					
							-4-
accessories found/se	ories used to perpetuate the et. Describe measuring point	on bear	of the ring tre	corner. Inc es. Show	any topogr	n view arawing and indic aphic features that woul	d d
aid in future recover $9.34$ x $30$ r	y of the comer. ebar set flush with ground	t					
	3	,	1			N . FD15 40	
	PINE	}	12			Notes FB17-49	١
	TLANTATION		12 GRAVES				
	PINE PLANTATION 3			"/	\$ 4 B	RASS CAP IN CONC AND Q S. EDGE	
	مارية		RADWAY 1	73 34.60	Fox	MD Q S. EDGE WER POLE	↓
1	RUAD SIGN 2.5 N89°00' E		N N	34.60		TONE WITH CHISELED	40
(ASSUMED	2.5 N89°0 30 W			587°41'33 35.89		X SET AS WM	Ÿ
17		34			X 2.5 E	-··×-	ŀ
FND I" IRON PIPE	0.00 × 0.		15	IW CONNET -33-12	2		ı
7,200	# 18 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		5	ET Z"IP YBRASS CH		REE PLANTATION	
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	-	1-		· <del>/</del>		
	ROAD SIGN				GATE		
			1-	10	*		
	\	1	/	8/13			
	\	1 \ /	/	12/2 W			
	\	! \/	,	b 2	<u>.</u> *		
	,	1		_		The NORTHWEST	_
	•	1	S	URVEYORS	SEAL	corner of Section $5$	-
				-67306236238EE3	410000	T. 33 N., R. 12	Ē. <b>7</b>
			\$10E.3	'sco/	VS June	Langlade County, W	ĐΕX
DAVID E. TLUST	74	1	Fire of	S CONTRACT	E		INDEX No.
I, LANGLADE COUN	<i>vry SuRVtYOR</i> , certify that wn on this record was determ	the ined	in it	TLUST	Y		L
by me or under my	direction and control and the rvey Monument Record is core	at this	肥	S-139 ANTIG		<b>]</b>	111
and complete to th	e best of my knowledge and	belief.		DAVID TLUST S-139 ANTIG WIS.			
13	1 1	/	THIN	AED	L'ELLANDE		1 0
1/1/9	Musta 8/12/9	99	.0	William LAN	1431111111	O=Location of corne	$ \mathcal{V} $
Signature	Date	<del></del>		-			ł
	· ·						

## WISCONSIN ADMINISTRATIVE CODE

A-E 7.07 Monuments. The type and position of monuments to be set on any survey shall be determined by the nature of the survey, the permanency required, the nature of the terrain, the cadastral features involved, and the availability of material. History: Cr. Register, February, 1987, No. 374, eff. 3-1-87.

- A-E 7.08 U.S. public land survey monument record.

  (1) WHEN MONUMENT RECORD REQUIRED. A U.S. public land survey monument shall be prepared and filed with the county surveyor's office as part of any land survey which includes or requires the perpetuation, restoration, reestablishment or use of a U.S. public land survey corner, and,
- (a) There is no U.S. public land survey monument record for the corner on file in the office of the county surveyor or the register of deeds for the county in which the corner is located; or,
- (b) The land surveyor who performs the survey accepts a location for the U.S. public land survey corner which differs from that shown on a U.S. public land survey monument record filed in the office of the county surveyor or register of deeds for the county in which the corner is located, or,
- (c) The witness ties or U.S. public land survey monument referenced in an existing U.S. public land survey monument record have been destroyed or disturbed.
- (2) FORM REQUIRED. A U.S. public land survey monument record shall be prepared on the board-approved form or on a form substantially the same as the board-approved form which includes all the elements required by this section. A form used for this purpose shall be entitled, "U.S. Public Land Survey Monument Record".

Note: A copy of the board-approved form is available from the Department of Regulation and Licensing, Bureau of Business and Design Professions, 1400 East Washington Avenue, P.O. Box 8935, Madison, Wisconsin 53708.

- (3) MONUMENT RECORD REQUIREMENTS. A U.S. public land survey monument record shall show the location of the corner and shall include all of the following elements:
- (a) The identity of the corner, as referenced to the U.S. public land survey system;
- (b) A description of any record evidence, monument evidence, occupational evidence, testimonal evidence or any other material evidence considered by the surveyor, and whether the monument was found or placed;
- (c) Reference ties to at least 4 witness monuments. Witness monuments shall be concrete, natural stone, iron, bearing trees or other equally durable material, except wood other than bearing trees:
- (d) A plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed:
- (e) A description of any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished;
- (f) Whether the corner was restored through acceptance of an obliterated evidence location or a found perpetuated location;
- (g) Whether the corner was reestablished through lost-corner-proportionate methods;
- (h) The directions and distances to other public land survey corners which were used as evidence or used for proportioning in determining the corner location; and,
- (i) The stamp and signature or seal and signature of the land surveyor under whose direction and control the corner location was determined and a statement certifying that the U.S. public land survey monument record is correct and complete to the best of his or her knowledge and belief.

History: Cr. Register, February, 1987, No. 374, eff. 3-1-87; am. (1) and (3) (c), Register, May, 1989, No. 401, eff. 6-1-89.