

CERTIFIED LAND CORNER RESTORATION

34-12

Index No. W-17

State of Wisconsin }
County of LANGLADE } ss.

History of original corner establishment:

I Wm. F. Kelly, do hereby certify that on the 1ST day of JULY, 1974, I found evidence of the NORTH 1/4 corner of SECS. 34 & 35 Township 34, North, Range 12 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

FOUND OLD SQD. STAKE ROTTED OFF AT GROUND
FENCE POSTS HAD BEEN SET AROUND STAKE



William F. Kelly
1 July 1974

Resident witnesses:



ROLAND JANSEN

Mrs. WOLHAUPT

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 1 1/2" PIPE w/ BRASS CAP MKD
PLACE MOUND OF ROCKS ABOUT POST.

- 1 = MAPLE 12 58 1/2 W 13.6'
- 2 = ELM 16 327 W 23.0'
- 3 = BASSWOOD 16 558 E 17.6'



○ = Corner monument restored.

Dated at ELCHO, Wis., this 1ST day of JULY, 1974

Signature William F. Kelly Title REG. LAND SURVEYOR Registration No. S-1098
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy