

CERTIFIED LAND CORNER RESTORATION

83-13

Index No. A-21


State of Wisconsin }
County of Lenglade } ss.

I Raymond J. Hallisy, do hereby certify that on the 28th day of June, 19 69, I found evidence of the Section corner of 35, 36, 2, 1. Township 33, North, Range 13E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

JERRY WEIX

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.


History of original corner establishment:

Corner set by Sperhake R.L.S. 463 12/11/62

Description of corner evidence found:

1 1/2" iron pipe with 4" cap.

T 33-34 N



R 13 E

SPERHAKE - RLS 463

Description of monument and accessories I established to perpetuate the original location of this corner.

No monument set.

B.T.'s to his pipe

Aspen 10" N62° 32 Feet 6 Inches

P.T.'s faced at base of tree and scribed PT

Dated at Antigo, Wis., this 28th day of June, 19 69.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy