State of Wisconsin

of March , 19 81, I found evidence of the Section corner of XXX 1, 6, 31, & 36

Township 34 & 35 , North, Range 9E , Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories

as described hereon to perpetuate the original

SS.

Resident witnesses:

location of this corner.

•••••	 •••••	

TJ4N RGE

R 9E	 	
Sec	 <i>3 </i> 	
R96	 	
 S	6	
	Sec	

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No.

History of original corner establishment:

Description of corner evidence found:

2" iron pipe with brass cap, 6" pipe post painted white with green top, S2E 3'1". Old BT Yellow birch S43E 35'2".

Description of monument and accessories I established to perpetuate the original location of this corner.

New BT's

12" Cedar S58W 30'2" 10" Cedar S38E 33'1" 4" Yellcw Birch N53E 9'9"

133	EN RGE
530	531
Si	56
134	N R9E

Dated at ____Antigo _____, Wis., this ___7th ____day of ____March ____, 19.81 ___

Signature County Surveyor, Registered Land Surveyor, or other duly authorized official)

(Register of Deeds)

By.....Deputy