U.S. PUBLIC LAND SURVEY MONUMENT RECORD (Prepared and as required by S. A-E 7.08 W Administrative Code)

The <u>NORTH QUARTER</u> corner of Section <u>3</u> , T. <u>34</u> N., R. <u>10</u> E., Langlade County, W
Corner was: (check all that apply) Restored through acceptance of an obliterated evidence location. Restored through acceptance of a found perpetuated location. Determined to be lost and re-established through proportionate methods. (Show bearings and distances to PLSS corners used for proportioning.) Restored/recovered/reestablished in a location that differs from a previously established position. (Show difference in plan view below.)
☐ Check here if additional information is shown on the reverse side of this form. Describe record evidence, recovered physical evidence, occupational evidence, testimonial evidence and all other evidence considered in the recovery/restoration of the corner.
The original corner was established in 1859 by Hiram C. Fellows. Original bearing trees: pine, 10", S20°W, 10 ks., and a birch, 8", N5°E, 10 lks. 1937 D. A. Hintz retraced original govt. survey and found the orig. pine 10" (20°W 10 lks., set new BT's: hemlock, 10", S69°E, 35.2 lks. and a red oak, 10", N83-1/4°W, 39.5 lks. and nade chiseled cross's: on the west slope of large rock S88-1/2°E, 41 lks., and on the top of a grey stone S40°W, 8.8 lks. July 1990 William F. Kelly found 4" brass cap monument and all of Hintz's BT's and made one new BT: hemlock, 12", N75°E, 8.97'. 10/15/98 D. Tlusty, D. Williams found 4" monument in good condition on high ground, surrounded by open bog to the east, south and west.
Physical description of the monument set:
Set white vinyl sign post 0.4' north of existing monument.
Describe the accessories used to perpetuate the location of the corner. Include a plan view drawing and indicate accessories found/set. Describe measuring point on bearing trees. Show any topographic features that would lid in future recovery of the corner. Bearings magnetic with hand compass. Notes FB 16-58 F = PK found or set in side of tree shown
WOODED WO
The NORTH QUARTER
SURVEYORS SEAL corner of Section 3
DAVID E. TZUSTY CANGCADE COUNTY SULVENCERTIFY that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief. Date T. 34 N., R. 10 E. Langlade County, WI NO AND E. Langlade County, WI OAVID E. Langlade County, WI OBEN 200 OAVID E. Langlade County, WI OBEN 200 OAVID E. Langlade County, WI OAVID E. Langlade County, WI OAVID E. Langlade County, WI OBEN 200 OAVID E. Langlade County, WI OAVID E. Langlade County, WI OBEN 200 OAVID E. Langlade County, WI OAVID E. Langlade County, WI OBEN 200 OAVID E. Langlade County, WI OAVID E. Langlade County, WI OBEN 200 OAVID E. Langlade County, WI OBEN 200 OAVID E. Langlade County, WI OAVID E. Langlade County, WI OBEN 200 OAVID E. Langlade County, WI OAVID E. Langlade County, WI OBEN 200 OAVID E. Langlade County, WI OAVID E. Langlade County, WI OBEN 200 OAVID E

WISCONSIN ADMINISTRATIVE CODE

A-E 7.07 Monuments. The type and position of monuments to be set on any survey shall be determined by the nature of the survey, the permanency required, the nature of the terrain, the cadastral features involved, and the availability of material. History: Cr. Register, February, 1987, No. 374, eff. 3-1-87.

A-E 7.08 U.S. public land survey monument record. 1) WHEN MONUMENT RECORD REQUIRED. A U.S. public land sur-

- (1) When MONUMENT RECORD REQUIRED. A U.S. public land survey monument shall be prepared and filed with the county surveyor's office as part of any land survey which includes or requires the perpetuation, restoration, reestablishment or use of a U.S. public land survey corner, and,
- (a) There is no U.S. public land survey monument record for the corner on file in the office of the county surveyor or the register of deeds for the county in which the corner is located; or,
- (b) The land surveyor who performs the survey accepts a location for the U.S. public land survey corner which differs from that shown on a U.S. public land survey monument record filed in the office of the county surveyor or register of deeds for the county in which the corner is located; or,
- (c) The witness ties or U.S. public land survey monument referenced in an existing U.S. public land survey monument record have been destroyed or disturbed.
- (2) FORM REQUIRED. A U.S. public land survey monument record shall be prepared on the board-approved form or on a form substantially the same as the board-approved form which includes all the elements required by this section. A form used for this purpose shall be entitled, "U.S. Public Land Survey Monument Record".

Note: A copy of the board-approved form is available from the Department of Regulation and Licensing, Bureau of Business and Design Professions, 1400 East Washington Avenue, P.O. Box 8935, Madison, Wisconsin 53708.

- (3) MONUMENT RECORD REQUIREMENTS. A U.S. public land survey monument record shall show the location of the corner and shall include all of the following elements:
- (a) The identity of the corner, as referenced to the U.S. public land survey system;
- (b) A description of any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence considered by the surveyor, and whether the monument was found or placed;
- (c) Reference ties to at least 4 witness monuments. Witness monuments shall be concrete, natural stone, iron, bearing trees or other equally durable material, except wood other than bearing trees;
- (d) A plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed;
- (e) A description of any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished;
- (f) Whether the corner was restored through acceptance of an obliterated evidence location or a found perpetuated location;
- (g) Whether the corner was reestablished through lost-cornerproportionate methods;
- (h) The directions and distances to other public land survey corners which were used as evidence or used for proportioning in determining the corner location; and,
- (i) The stamp and signature or seal and signature of the land surveyor under whose direction and control the corner location was determined and a statement certifying that the U.S. public land survey monument record is correct and complete to the best of his or her knowledge and belief.

History: Cr. Register, February, 1987, No. 374, eff. 3-1-87; am. (1) and (3) (c), Register, May, 1989, No. 401, eff. 6-1-89.

U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).


(a) Identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.

1859 - H.C. FELLOWS EST, ORIG COR.

1937 - D.A. HINTZ RESURVEYED SECT. 34 & Found ORIG. Pine 8T. MADE NOTS: 10" Hemlock, 569° 35.21ks 10"OAK, N83% W, 39.5 ks.

CROSS ON W. Slope large Rock, SBBYEE, 41KS.
"Top of Grey STONE, 540" , 5.8 lks





(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.


JULY, 1990 I FOUND 4" BRASS CAP MONUMENT & ALL OF HINTZ'S BTS. MADE ONE NBT.


- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)

 Describe witness monuments.
- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.









Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that
corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing
under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as
restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

140	44	<u>-</u>
K U	~	1=

(f)	Was the corner restored through a	ccentance of (1) an obliterated evidence location, or,	(2) a found ne	rnetuated location 2
117	was the corner restored through a	cceptance of ()	j an obliterated evidence location, or,	(Z) a loully pe	ri petuateu location. :

FOUND PERPETUATED LOCATION

Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner (g & h) location.

(type or print name)

certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

WILLIAM F. **KELLY S1098** ELCHO,