O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. A - 7

History of original corner establishment:

Original corner established by Hiram C. Fellows, Deputy Surveyor, in 1859, from which Fir 8" bears N 55° E, 17 links and Sugar 8" bears S 85° W, 18 links.

H.C. Lawrence, Registered Land Surveyor, searched for but was unable to recover any evidence of this corner in 1952. Did find an old squared aspen on N-S blazed line which was questionable.

Description of corner evidence found:

No evidence of any corner recovered. Corner established by traverse and computation. R_{an} traverse from section corner 31, 32, 6 and 5 (recovered old iron pipe projecting 24" which Wm. Kelley, Langlade County surveyor, stated had been recognized and used by local land surveyors for years) east 5604.256 feet to section corner 4, 5, 32, 33. Computed bearing N 89° 13' 25" E. Set corner at 2802.128 feet intermediate.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 21" iron pipe with screw-in brass cap (Langlade County).

Monument projects 18" above ground. Cap stamped:

Marked NBT's -

Sugar	6"	S82°E	69.981	T35N R11E
W.Birch				$1/4 \frac{s}{s} + \frac{32}{5}$
W.Birch				1/4 s 5
W.Birch	8"	N45°W	36.01	T34N R11E
all s	crib	ed 1/4	BT	S498 - 1978

Dated at	Rhinelander	, Wis., this.	4th	day of	December	19. 78
Signature.	Hulp Hanson. County Surveyor, Registere	Title d Land Surve	Registered	Land Surve	yor Registra	tion No. S-498
Office of Reg instrument v	gister of Deeds, County of vas filed in this office for reco 'clock		ranglade		, I hereby cert	ify that the withir
•••••	(Register of Deeds)			-		