## LAND SURVEY MONUMENT RECORD PUBLIC U.S.

INSTRUCTIONS.


This record shall show the location of the corner and shall include all of the following nine elements (a through i).

(a) Identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.

ORIGINAL CORNER ESTABLISHED BY HIRAM C FELLOWS MAY 1859 URIG BT ASH 10 NIOW JELKS 30 LKS

LOCATED SCRIBED ROBERT POSS 5" WOOD POST AND I'L" IRON PIPE AND SET I" IRON PIPE WITH BRASS CAP AT CORNER IN 1967



TN 35N RILE

TRIPLE BASSWOOD 12"


Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

LOCATED SET P.K. NAIL IN BASE OF R. POSS -BRASS SAP SET BY WITHESS TREES I" FO WIT MOIN. AND SET

In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a (c) municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.) BRASS CAP COUNTS Describe witness monuments. SWEIDA

(d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

0



7

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that
corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing
under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as
restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

NONE

(f)	Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location.?
	(2)

(g & h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

NONE

(i) I WILLIAM F KELLY RLS 1098

(type or print name)
certify that the corner location shown on this record was determined by me or under
my direction and control and that this U.S. Public Land Survey Monument Record is
correct and complete to the best of my knowledge and belief.

6-19-90 Date Affix Land Surveyor Seal

WILLIAM F. KELLY S1098 ELCHO,

Milliam T. Killy

State of Wisconsin
County of LANGLADE ss.
I, ROBERT J. Poss do hereby certify that on the day of July 19.67, I found evidence of the NORTH 4 corner of SECTION 3  Township 34 North, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original
location of this corner.  Resident witnesses:
34
POLLOCK POLLOC

	3		A.CoR
Pol	ock		  bst Lake 
	     	To the	6010
	i — — — — — — — — — — — — — — — — — — —	i i	
	<del> </del>	¦	 1 1

O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

Index No. 4-15

Index No. 4-15

ROBERT

POSS
S-0001

ELCHA HISTMEN

Description of corner evidence found:

SQD STAKE - 5"SQ. MKD" 53" ON SOUTH SIDE; SEC.34" ON NORTH; /4 COR" ON WEST SIDE; GOOD COND. 12" PIPE ALONGSIDE; ON E.SIDE TOWN ROAD

Description of monument and accessories I established to perpetuate the original location of this corner.

SET I" IRON PIPE WITH BRASS CAP MKD:

ONEIDA COUNTY

SEC. 34

TH 35N || R IIE

TH 35N || R IIE

SEL. 36

TH 35N || R IIE

X OLD BLAZE ON 10" HD. MAPLE N 26" E 14.2'

X OLD BLAZE ON 12" HD. MAPLE S52° E 21.3'

X 3 BLAZED CTR. TREE TRIPLE BASSWOOD 12" EA.

S28° E 34.7

By......Deputy